

PROJECT DETAILS

JOB NUMBER	KEF462	CLEARANCE DATE	31/05/2017	
CLIENT	AGH Demolition & Asbestos Removal	REPORT DATE	31/05/2017	
CONTACT NAME		CONTACT NUMBER		
SITE ADDRESS	Jaeger 1 Building, Australian National University (ANU) - Mills Road, Acton, ACT 2601			
SCOPE OF WORKS	Environmental clean of Room B1 (Instrument room) and Lift Cabin in Basement Corridor.			
SCOPE OF CLEARANCE	A thorough visual inspection and clearance air monitoring was conducted.			
ASBESTOS CONTRACTOR	AGH Demolition & Asbestos Removal	SUPERVISOR		
ASBESTOS ASSESOR		LICENCE NUMBER	LAA001255	
LEGISLATION	Asbestos removal clearance certificate issued under regulations 473 & 474 of the Work Health Safety Regulation 2011			

VISUAL CLEARANCE

	YES	NO	N/A
Did inspection of the specific work area detailed above find no visible dust remaining as a result of the remediation work carried out?	✓		
Did inspection of the internals of the site find no visible dust remaining as a result of the remediation work carried out?	✓		
Is air monitoring required?	✓		
Can the site be dismantled?	✓		
Did inspection of the work area following dismantling of the enclosure find no visible dust remaining?			
Can the area be reoccupied?	\checkmark		

CONCLUSION

A thorough visual inspection of Room B1 and the lift cabin found no visible residue from remediation work in the area or in the vicinity of the area where the work was carried out.

This area has been cleared for reoccupation, and restrictions associated with the asbestos work can now be lifted.

Kind Regards,

Gleane

Lab Manager



PHOTOS



Remediation area - Lift




Remediation area - Lift



Remediation area - Room B1



Remediation area - Lift



Remediation area - Room B1



Remediation area - Room B1



PHOTOS-1



Remediation area - Room B1



Remediation area - Room B1



Remediation area - Room B1



Remediation area - Room B1



Remediation area - Room B1



Remediation area - Room B1