

PROJECT DETAILS

JOB NUMBER	KEF462	INSPECTION DATE	17/07/2017	
CLIENT	AGH Demolition & Asbestos Removal	REPORT DATE	17/07/2017	
CONTACT NAME	Brett Gibson	CONTACT NUMBER	+61402882305	
SITE ADDRESS	Jaeger 1 Building, Australian National University (ANU) - Mills Road, Acton, ACT 2601			
SCOPE OF WORKS	Removal of friable asbestos pipe lagging to stage two area in the basement.			
ASBESTOS CONTRACTOR	AGH Demolition & Asbestos Removal	SUPERVISOR	John coulter	
ASBESTOS ASSESOR	Ged Keane	LICENCE NUMBER	LAA001142	
LEGISLATION	A thorough visual inspection of the enclosure was conducted followed by a smoke test as per section 5.2 Testing an enclosure of the Code of Practice How to Safely Remove Asbestos (2011),			

ENCLOSURE CHECKS

	YES	NO	N/A
Is the asbestos work area and the asbestos removal site clearly defined?	\checkmark		
Is the enclosure constructed of heavy-duty plastic sheeting (200 µm minimum thickness)?			
Does enclosure integrity appear OK?	\checkmark		
Smoke test Conducted?	\checkmark		
Is air flow management adequate to disperse the smoke sufficiently?			
Did the smoke test reveal any leaks?			
Have the leaks been repaired?			
Does the negative air pressure unit(s) exhaust the enclosure efficiently?			

CONCLUSION

The enclosure was retested around the negative pressure units and found to be in good condition and airtight. It is satisfactory for works to continue.

Kind Regards,


9 Keane

Ged Keane


Lab Manager



PHOTOS



Negative pressure unit



Negative pressure units end of enclosure